



Tom Barrett  
Mayor

Bevan K. Baker, FACHE  
Commissioner of Health

Vivian T. Chen, MSW, ScD  
Health Operations Director

## Health Department

## Consumer Environmental Health

Frank P. Zeidler Municipal Building, 841 North Broadway, Room 304, Milwaukee, WI 53202-3653 Phone: (414) 286-3674 Fax: (414) 286-5164  
web site: [www.milwaukee.gov/health](http://www.milwaukee.gov/health)

# Routine Food Inspection

Reinspection #1

MILWAUKEE KICKERS SOCCER CLUB, INC.  
MILWAUKEE KICKERS SOCCER CLUB (OUTDOOR FIELD BUILDING)  
7101 W GOOD HOPE RD  
MILWAUKEE, WI 53223

July 2, 2007

The following list of violations of the Wisconsin Administrative Code as adopted by reference in the Milwaukee Code of Ordinances Chapter 68, and/or other City ordinance(s) must be corrected as soon as possible but not later than the date specified. A re-inspection fee may be assessed if the violation is not corrected by that date. An inspection fee may be charged for any repeat violations.

**Fee Amount:** \$74.00

Code Number	Description of Violation	Correct By
12-201.11(C)	No food manager's certificate posted. Post the State certificate for your certified food manager	07/09/2007
5-202.11	No air gap installed on the ice bin drains. To prevent sewage backflow from entering the ice bin, install an air gap for both ice bin drains.	07/09/2007
4-501.11	Observed a leak underneath the left sink basin at the warewash sinks. Repair the drainage leak to code to ensure that it no longer leaks. The women's restroom has a stall that is out of order. Repair the toilet to code to ensure that it is functional.	07/09/2007
6-501.114	There is a hole in the wall next to the slushy machine. Repair the hole with a smooth and cleanable surface. Wood is not approved and cannot be used for the repair. There is also a burner that is sitting on the floor in the cook area. Provide a stainless steel table for the burner or remove the burner from the premises.	07/09/2007

### Inspection Notes

Notes: Ice bin drain line being held up using a wood block. Wood is not approved to hold up the drain. Properly install the air gap for the ice bin drain. The other ice bin drain is not air gapped. The end of the drain cannot enter into the funnel drain. There must be a gap between the drain and the funnel. Properly install an air gap.

Provide a stainless steel table for the burner in the kitchen or remove the burner from the premise.



Tom Barrett  
Mayor

Bevan K. Baker, FACHE  
Commissioner of Health

Vivian T. Chen, MSW, ScD  
Health Operations Director

## Health Department

## Consumer Environmental Health

---

Frank P. Zeidler Municipal Building, 841 North Broadway, Room 304, Milwaukee, WI 53202-3653 Phone: (414) 286-3674 Fax: (414) 286-5164  
web site: [www.milwaukee.gov/health](http://www.milwaukee.gov/health)

On 7/2/2007, I served these orders upon MILWAUKEE KICKERS SOCCER CLUB, INC. by leaving this report with

Inspector Signature (Inspector ID: 66)

Operator Signature

Please be advised that this document is subject to public review under open records law. - Wis. Statutes section 19.35(1)(a)